

April 14, 1987

TO: File

FROM: Frank Jensen, Soils Reclamation Specialist *Jensen*

RE: Kent R. Dahl, DOE/O47/O31

On March 24, 1987, Frank Filas, David Wham, and I inspected the subject placer mining operation. It is within the Horseshoe Bend area of the Green River.

The equipment on this operation is far above average with mostly new mining machinery.

Photos of the operation follow:



Photo mosaic of the processing equipment. The Green River is in the background at the base of the steep hillside.

Page 2
Kent R. Dahl, DOE/O47/O31
April 14, 1987



Photo of camper living quarters and piles of old placer material that was evidently worked years ago. It appears they are reprocessing some of the material from the large pile in the background.

clj
1115R/74-75

